

File: ULC Subject S529, C386 ULC-G.5.2

February 9, 2016

CERTIFICATION BULLETIN CCH-2016-102

To: Subscribers/Listees to ULC's Listing Service for Flame Detectors, Fire Alarm, for Use in Hazardous Locations (UIAZC)

Subject: Harmonization of Flame Detectors, Fire Alarm, for Use in Hazardous Locations (UIAZC) with Flame-automatic Fire Detectors for Use in Hazardous Locations Certified for Canada (UIAZ7)

UL as an enterprise is striving to offer to its customers combined Canadian Certification Directories. In doing so, Underwriters Laboratories of Canada Inc. (ULC) and UL LLC are harmonizing their Canadian Certification categories in order to come up with a single Canadian Listing Directory for certified (Listed) products.

Consequently, UL is harmonizing the certification category Flame Detectors, Fire Alarm, for Use in Hazardous Locations (UIAZC) with the certification category Flame-automatic Fire Detectors for Use in Hazardous Locations Certified for Canada (UIAZ7). As the category UIAZC is being harmonized, the Product Listings that are currently certified under UIAZC will now be under UIAZ7.

The harmonized categories will represent manufacturers who received authorization from ULC and UL LLC to use their respective marks for Canada.

There are certain administrative activities that are taking place; one such activity is harmonizing the Category Control Numbers (CCN's, an internal terminology used for tracking) resulting in a combined Canadian Listing Directory. Any necessary revisions to your File will be notified and will be at no charge to you. We anticipate completing this transition by March 31, 2016.

Your Field Representative can assist you with any questions regarding the change in category. If you have additional questions please contact Ken Boyce via phone at (847) 664-2318, or email Kenneth.P.Boyce@ul.com.

Please share this Bulletin with other interested parties within your organization.

Sincerely,

Issued under the joint responsibility of Underwriters Laboratories of Canada Inc. & UL LLC. This Bulletin has been reviewed and approved by:

Ken BoyceEngineering Leader

Global Hazardous Locations

Paul T. Kelly
Principal Engineer
Global Hazardous Locations

Gunsimar Paintal

Regional Manager - Accreditation & Quality ULC Mark Program Owner

Underwriters Laboratories of Canada Inc. 7 Underwriters Road, Toronto, ON M1R 3A9, Canada T: 416.757.3611 / F: 416.757.9540 / W:ULC.ca Version 2.0, September 9, 2015