

File: ULC Subject S507 ULC-G.5.2

March 28, 2016

CERTIFICATION BULLETIN CCH-2016-122

To: Subscribers/Listees to ULC's Listing Service for Antifreeze Solution Extinguishers (FWTXC)

Subject: Harmonization of Antifreeze Solution Extinguishers (FWTXC) with the new certification category Antifreeze Solution Extinguishers Certified for Canada (FWTX7)

UL as an enterprise is striving to offer to its customers combined Canadian Certification Directories. In doing so, Underwriters Laboratories of Canada Inc. (ULC) and UL LLC are harmonizing their Canadian Certification categories in order to come up with a single Canadian Listing Directory for certified (Listed) products.

Consequently, UL is harmonizing the certification category Antifreeze Solution Extinguishers (FWTXC) by establishing a new certification category Antifreeze Solution Extinguishers Certified for Canada (FWTX7). As the category FWTXC is being harmonized, the Product Listings that are currently certified under FWTXC will now be under FWTX7.

The harmonized categories will represent manufacturers who received authorization from ULC and shall continue using the authorized mark for Canada.

There are certain administrative activities that are taking place; one such activity is creating a new Category Control Numbers (CCN's, an internal terminology used for tracking). Any necessary revisions to your File will be notified and will be at no charge to you. We anticipate completing this transition by September 30, 2016.

Your Field Representative can assist you with any questions regarding the change in category. If you have additional questions please contact Daniel R. Weaver via phone at (847) 664-1462, or email Daniel.R.Weaver@ul.com.

Please share this Bulletin with other interested parties within your organization.

Sincerely,

Issued under the joint responsibility of Underwriters Laboratories of Canada Inc. & UL LLC. This Bulletin has been reviewed and approved by:

Daniel R. Weaver **Engineering Leader** BLST, Fire Suppression

Blake M. Shugarman Principal Engineer BLST, Fire Suppression

Gunsimar Paintal

Regional Manager - Accreditation & Quality **ULC Mark Program Owner**

Underwriters Laboratories of Canada Inc. 7 Underwriters Road, Toronto, ON M1R 3A9, Canada T: 416.757.3611 / F: 416.757.9540 / W:ULC.ca

Version 2.0, September 9, 2015